IMPORTANT SAFETY AND INSTALLATION INSTRUCTIONS for future use. Make sure installation and These instructions do not claim to cover

all connections are in accordance with

National Electrical Code and any local

service personnel.

regulations. To avoid possible electrical

shock, be sure that power supply is turned

off before installing or servicing this fixture.

Servicing should be performed by qualified

all details or variations. When additional

information is desired, please contact

vour SPI representative.

WARNING: Risk of fire and electrical shock. This product is to be installed by a qualified electrician only.

CAUTION: When using electrical equipment, basic safety precautions should always be followed including the following: Read all instructions carefully before installation and save

NOVATO ORBIT

J-BOX (BY OTHERS) ASSEMBLE LARGE OUTER RING SEGMENTS. MOUNT CANOPY MOUNTING PLATE OVER J-BOX (BY OTHERS) INTO STRUCTURAL CANOPY SUPPORTS (BY OTHERS) USING HARDWARE (BY OTHERS). MOUNTING 3. MOUNT STANDOFF PLATE TO CANOPY MOUNTING PLATE USING HARDWARE PLATE PROVIDED, THEN ATTACH CANOPY SPINNING. 4. RAISE RINGS AND MOUNT TO AIRCRAFT CABLES FROM MOUNTING HUB. ENSURE PROPER CABLE PATTERN IS MAINTAINED. STANDOFF 5. LEVEL LARGE OUTER RING AND ROTATE MIDDLE AND INNER RINGS TO DESIRED PLATE ANGLES. ***CAUTION*** AIRCRAFT CABLES MUST NOT TOUCH RINGS AS THIS MAY CAUSE CABLES TO FRAY. TAKE CARE NOT TO ROTATE FIXTURES TOO FAR. CANOPY 6. RUN POWER CORDS INTO MOUNTING HUB, UP INTO CEILING AND TO REMOTE SPINNING BOXES. STRAIN RELIEFS SHOULD BE ATTACHED TO EACH CORD INSIDE OF HUB. 7. ATTACH POWER CORDS TO POWER SUPPLIES WITH CORRESPONDING CONNECTION LABELS. MOUNTING HUB AIRCRAFT CABLES ON ALL RINGS MUST CABLES BE AT LEAST 45' TO FIXTURE MIN 45 DETAIL A SCALE 1/4 FIGURE 1

SPI LIGHTING

09/28/2022 IS86798X