

IMPORTANT SAFETY AND INSTALLATION INSTRUCTIONS

WARNING: Risk of fire and electrical shock. This product is to be installed by a qualified electrician only.


CAUTION: When using electrical equipment, basic safety precautions should always be followed including the following: Read all instructions carefully before installation and save

for future use. Make sure installation and all connections are in accordance with National Electrical Code and any local regulations. To avoid possible electrical shock, be sure that power supply is turned off before installing or servicing this fixture. Servicing should be performed by qualified service personnel.

These instructions do not claim to cover all details or variations. When additional information is desired, please contact your SPI representative.

POWER CORD SUSPENSION (PCS)

1. FEED POWER CABLE UP THROUGH CANOPY AND CROSS BAR.
2. ADJUST LENGTH OF CORD FOR DESIRED OAH THEN CRIMP ON STRAIN RELIEF.
3. TWIST AND LOCK CROSS BAR TO J-BOX AND SECURE BY TIGHTENING THE SCREWS (BY OTHERS.)
4. WIRE CONNECTIONS, PER LOCAL CODE.
5. SECURE CANOPY TO CROSS BAR BY PUSHING UPWARD AND SNAP IN PLACE.



SPI

08/03/17
IS99350X

SPILIGHTING

10400 N. Enterprise Drive, Mequon, WI. 53092 262 242 1420 FAX: 262 242 6414