

IMPORTANT SAFETY AND INSTALLATION INSTRUCTIONS

WARNING: Risk of fire and electrical shock. This product is to be installed by a qualified electrician only.


CAUTION: When using electrical equipment, basic safety precautions should always be followed including the following: Read all instructions carefully before installation and save

for future use. Make sure installation and all connections are in accordance with National Electrical Code and any local regulations. To avoid possible electrical shock, be sure that power supply is turned off before installing or servicing this fixture. Servicing should be performed by qualified service personnel.

These instructions do not claim to cover all details or variations. When additional information is desired, please contact your SPI representative.

LBI / LBK WET LOCATION MOUNTING, STYK

MOUNTING ARM WITHOUT POWER



1. APPLY A GENEROUS SEAL OF SILICONE (OR EQUIVILENT) AROUND THE OUTER MOUNTING SURFACE OF THE MOUNTING PLATE.
2. FASTEN THE MOUNTING PLATE TO THE JUNCTION BOX (FASTENERS BY OTHERS)
3. APPLY SILICONE (OR EQUIVILENT) TO ALL OF THE HOLES AND SCREWS IN MOUNTING PLATE.
4. SLIDE THE COVER OVER THE MOUNTING PLATE AND SECURE WITH FLAT HEAD SCREWS (PROVIDED).

MOUNTING ARM WITH POWER

1. REMOVE ACCESS COVER AND PULL LEAD WIRES FROM THE FIXTURE AND POWER LEADS FROM THE WALL THRU THE HOLE.


2. APPLY A GENEROUS SEAL OF SILICONE (OR EQUIVILENT) AROUND THE OUTER MOUNTING SURFACE OF THE MOUNTING PLATE.

3. FASTEN THE MOUNTING PLATE TO THE JUNCTION BOX (FASTENERS BY OTHERS)

4. MAKE SPLICE CONNECTIONS PER LOCAL CODES AND REPLACE ACCESS COVER WITH GASKET.

5. APPLY SILICONE (OR EQUIVILENT) TO ALL OF THE HOLES AND SCREWS IN MOUNTING PLATE.

6. SLIDE THE COVER OVER THE MOUNTING PLATE AND SECURE WITH FLAT HEAD SCREWS (PROVIDED).



8/5/15
IS91442X