

IMPORTANT SAFETY AND INSTALLATION INSTRUCTIONS


WARNING: Risk of fire and electrical shock. This product is to be installed by a qualified electrician only.

CAUTION: When using electrical equipment, basic safety precautions should always be followed including the following: Read all instructions carefully before installation and save

for future use. Make sure installation and all connections are in accordance with National Electrical Code and any local regulations. To avoid possible electrical shock, be sure that power supply is turned off before installing or servicing this fixture. Servicing should be performed by qualified service personnel.

These instructions do not claim to cover all details or variations. When additional information is desired, please contact your SPI representative.

MIA/MRA Mounting



INSTALLATION:

1. FASTEN MOUNTING PLATE ASSEMBLY TO JUNCTION BOX (BY OTHERS) USING SCREWS (BY OTHERS). FIXTURES MOUNTED WITH GREATER THAN 3 CABLES REQUIRE MOUNTING PLATE ASSEMBLY TO BE FASTENED USING AUXILIARY MOUNTING HOLES AND HARDWARE (BY OTHERS).
2. FEED POWER CORD THROUGH CANOPY CAP, CANOPY COVER, AND MOUNTING PLATE ASSEMBLY.
3. RAISE FIXTURE TOWARDS JUNCTION BOX AND INSERT BALL END OF CABLES INTO SLOTS ON MOUNTING PLATE. MAKE CONNECTIONS TO REMOTE DRIVERS, OR BRANCH CIRCUIT DEPENDING ON FIXTURE CONFIGURATION.
4. FASTEN CANOPY COVER IN PLACE USING CANOPY CAP.
5. MAKE NECESSARY HEIGHT ADJUSTMENTS, AND LEVEL THE FIXTURE USING INTERNAL AIRCRAFT GRIPPERS. TRIM EXCESS CABLE AFTER ESTABLISHING DESIRED HEIGHT.

12/10/20
IS109411X