

IMPORTANT SAFETY AND INSTALLATION INSTRUCTIONS

WARNING: Risk of fire and electrical shock. This product is to be installed by a qualified electrician only.

CAUTION: When using electrical equipment, basic safety precautions should always be followed including the following: Read all instructions carefully before installation and save


for future use. Make sure installation and all connections are in accordance with National Electrical Code and any local regulations. To avoid possible electrical shock, be sure that power supply is turned off before installing or servicing this fixture. Servicing should be performed by qualified service personnel.

These instructions do not claim to cover all details or variations. When additional information is desired, please contact your SPI representative.

SEGMENTED NOVATO CONNECTION - REMOTE

INSTALLATION STEPS:

1. CONNECT FIXTURES TOGETHER, ALLOWING FOR MAGNETIC COUPLING TO ENGAGE. (ASSEMBLE RING ON FLAT SURFACE)
2. FEED CORD THROUGH SPLICE BOX SO THAT POWER CORD CONNECTOR CAN BE COVERED BY THE SPLICE BOX WHEN INSTALLED.
3. MAKE POWER SPLICE USING INCLUDED WIRE CONNECTORS (REFERENCE IS100493X)
4. SECURE FIXTURES TOGETHER USING SPLICE BOX(S)
5. ADJUST AIRCRAFT CABLE TENSION TO DRAW FIXTURES TOGETHER.
6. USE SUPPLIED PLASTIC SHIM STOCK ON ONE SIDE OF SPLICE BOX TO DRAW IN ANY TROUBLESOME JOINTS.
7. WHEN USING SHIM STOCK, PLACE A STACK OF REQUIRED SHIMS NEXT TO EACH SCREW (SEE FIGURE 4), GENTLY SNUG SCREWS TIGHT, DO NOT OVERTIGHTEN.



06/18/2021
IS99202X