

IMPORTANT SAFETY AND INSTALLATION INSTRUCTIONS

WARNING: Risk of fire and electrical shock. This product is to be installed by a qualified electrician only.

CAUTION: When using electrical equipment, basic safety precautions should always be followed including the following: Read all instructions carefully before installation and save

for future use. Make sure installation and all connections are in accordance with National Electrical Code and any local regulations. To avoid possible electrical shock, be sure that power supply is turned off before installing or servicing this fixture. Servicing should be performed by qualified service personnel.

These instructions do not claim to cover all details or variations. When additional information is desired, please contact your SPI representative.

NOVATO RING-MONOPOINT MOUNT


INSTALLATION STEPS:

1. FASTEN CEILING MOUNTING PLATE ONTO JUNCTION BOX. ALSO, FASTEN PLATE TO CEILING USING AUXILIARY MOUNTING HOLES PROVIDED. MAKE INCOMING POWER CONNECTIONS PER LOCAL AND STATE CODES.
2. HANG STEM WITH BALL ON END INSIDE HANGING BRACKET ATTACHED TO CANOPY.
3. PULL ADJUSTABLE AIRCRAFT CABLES THROUGH ADJUSTABLE GRIPPERS ON FIXTURE. ADJUST FOR DESIRED HEIGHT.

4. RUN POWER CORD(S) ALONG AIRCRAFT CABLES, THROUGH CENTER OF TRANSITION HUB, AND THROUGH CANOPY. MAKE POWER CONNECTIONS TO POWER SUPPLY(S) USING PROVIDED WIRE NUTS. LABELS MAY BE ATTACHED TO WIRES TO INDICATE POWER SUPPLY CONNECTION.

5. FASTEN CANOPY OVER HANG BRACKET USING #8 FHMS PROVIDED.

***MOUNTING PLATE, CANOPY DETAILS AND FIXTURE DESIGN MAY VARY FROM THE ONE SHOWN.**



07/22/2020
IS79759X