

IMPORTANT SAFETY AND INSTALLATION INSTRUCTIONS

WARNING: Risk of fire and electrical shock. This product is to be installed by a qualified electrician only.

CAUTION: When using electrical equipment, basic safety precautions should always be followed including the following: Read all instructions carefully before installation and save


for future use. Make sure installation and all connections are in accordance with National Electrical Code and any local regulations. To avoid possible electrical shock, be sure that power supply is turned off before installing or servicing this fixture. Servicing should be performed by qualified service personnel.

These instructions do not claim to cover all details or variations. When additional information is desired, please contact your SPI representative.

HARBOR WET LOCATION PULL OUT LENS (INST2)

NOTES:

1. REMOVE FINIAL BALLS AND ROLL CAGE ASSEMBLY REMOVE SCREWS FOR MAIN LENS ASSEMBLY
2. MAKE ELECTRICAL CONNECTIONS IN ACCORDANCE WITH NATIONAL ELECTRIC CODE AND ALL LOCAL REGULATIONS.
3. SECURE FIXTURE TO WALL OVER 4" OCTAGONAL JUNCTION BOX (BY OTHERS) BY USING SIX (6) PROVIDED AUXILIARY MOUNTING HOLE LOCATIONS. MOUNTING HARDWARE BY OTHERS. *** FIXTURE MOUNTS OVER A J-BOX FOR POWER FEED CONNECTION BUT IS SUPPORTED INDEPENDENTLY OF J-BOX BY ATTACHING FIXTURE TO WALL. ***
4. REPLACE LENS AND SCREWS, CAGE AND FINIAL BALLS
5. APPLY GENEROUS AMOUNT OF SILICONE (OR EQUIVLENT) TO TOP AND SIDES OF FIXTURE



* DECORATIVE BARSTOCK AND ORIENTATION CONFIGURATION MAY VARY, DEPENDING ON BASE MODEL ORDERED.

7/15/19
IS104993X