## IMPORTANT SAFETY AND INSTALLATION INSTRUCTIONS

WARNING: Risk of fire and electrical shock. This product is to be installed by a qualified electrician only.


CAUTION: When using electrical equipment, basic safety precautions should always be followed including the following: Read all instructions carefully before installation and save for future use. Make sure installation and all connections are in accordance with National Electrical Code and any local regulations. To avoid possible electrical shock, be sure that power supply is turned off before installing or servicing this fixture. Servicing should be performed by qualified service personnel. These instructions do not claim to cover all details or variations. When additional information is desired, please contact your SPI representative.

## HARBOR WET LOCATION SLIDE OUT LENS (INST1)

## NOTES:

- 1. SEPARATE MAIN LENS ASSEMBLY FROM FIXTURE BY REMOVING TOP TWO (2) SCREWS. CAREFULLY SLIDE LENS UP AND OUT FROM TOP SIDE OF HOUSING FRAME.
- 2. MAKE ELECTRICAL CONNECTIONS IN ACCORDANCE WITH NATIONAL ELECTRIC CODE AND ALL LOCAL REGULATIONS.
- 3. SECURE FIXTURE TO WALL OVER 4" OCTAGONAL JUNCTION BOX (BY OTHERS) BY USING SIX (6) PROVIDED AUXILIARY MOUNTING HOLE LOCATIONS. MOUNTING HARDWARE BY OTHERS. \*\*\* FIXTURE MOUNTS OVER A J-BOX FOR POWER FEED CONNECTION BUT IS SUPPORTED INDEPENDENTLY OF J-BOX BY ATTACHING FIXTURE TO WALL. \*\*\*
- 4. REPLACE LENS AND SCREWS
- 5. APPLY GENEROUS AMOUNT OF SILICONE (OR EQUVILENT) TO TOP AND SIDES OF FIXTURE

NO SILICONE REQUIRED ON BOTTOM OF FIXTURE



7/15/19 IS104992X



ON BASE MODEL ORDERED.

\* DECORATIVE BARSTOCK AND ORIENTATION CONFIGURATION MAY VARY, DEPENDING